MasterList CD v2.3.1cs1 Update (For Macintosh)

Fix for MasterList CD v2.3 using Yamaha CDRW 8424S with firmware v1.0j

Should I Update?
MasterList CD v2.3.1cs1 should only be installed if you have the following components or are experiencing the dialog described below. MasterList CD v2.3.1cs1 should not be used for any other purpose.

If you currently have the following components in your system you should install the update to MasterList CD v2.3.1cs1:

- MasterList CD v2.3 application
- Yamaha CDRW 8424S with firmware **v1.0j** *(do not use the update if you have firmware v1.0g)*

MasterList CD v2.3.1cs1 stops the following dialog from appearing (which occurs with the above combination of components) after the "Write Disc" button is pressed: "Version 1.07, 1.08 of the CDR-100 requires copy flags on all tracks"

Drag and Drop Installation Instructions
This is not an auto-installer. This download consists of MasterList CD v2.3.1cs1 and this Read Me only. To install:

1. Make certain that MasterList CD is not running.
2. Locate the "MasterList CD" folder on your hard drive. It should be located within the "Digidesign" folder.
3. Drag & Drop the MasterList CD v2.3.1cs1 application called "MasterList CD™" into the "MasterList CD" folder on your hard drive.
4. A dialog stating the following should appear: "An older item named "MasterList CD™" already exists in this location. Do you want to replace it with the one you're moving?"
5. Click OK

Congratulations, you're done. Restarting your computer is not necessary.

Further Questions?
If you have any questions or comments, please contact us via our website: http://www.digidesign.com

November 17, 2000